



Flat surfaces of the pin must be connected parallel to the Main Axis